



HONDA




report date: 2024-03-28

General information

Make	HONDA
Model	ACCORD VTEC EX
Colour	Blue
Year of manufacture	2006
Top speed	141 mph
0 - 60 mph	8.0 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	222 Nm at 4.500 rpm
Engine capacity	2.354 cc
Cylinders	4
Fuel type	Petrol
Consumption city	20.6 mpg
Consumption extra urban	40.9 mpg
Consumption combined	30.1 mpg
CO2 emission	223 g/km
CO2 label	K






Internet history

Entry 1

Date	2022-04-03
Pictures	44
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-19
MOT pass rate	89 %
MOT passed	16
Failed MOT tests	2
Total advice items	16
Total items failed	6

MOT #18	2024-03-13 18:23
MOT test number	459006557562
Result	✓ Passed
Next expiry date	2025-03-19
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Front Tyre worn close to legal limit/worn on edge Both sides worn on edges only (5.2.3 (e))

MOT #17	2023-03-13 16:26
MOT test number	645872090371
Result	✓ Passed
Minor	Offside Rear Inner Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

MOT #16	2022-03-17 13:38
MOT test number	839568215519
Result	✓ Passed

MOT #15	2021-03-20 11:32
MOT test number	752986406874
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #14** 2021-03-19 13:29**MOT test number** 990519531336**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Windscreen washer not working (3.5 (a))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))**Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #13** 2020-03-16 16:41**MOT test number** 427777889519**Result** ✓ Passed**MOT #12** 2020-03-16 16:41**MOT test number** 254311131944**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #11** 2019-03-19 09:57**MOT test number** 170545353430**Result** ✓ Passed**MOT #10** 2018-03-20 09:46**MOT test number** 997495091737**Result** ✓ Passed**Advice** Covers & shields fitted not allowing full inspection

**MOT #9** 2017-04-06 13:58**MOT test number** 602719791158**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Covers & shields fitted not allowing full inspection**Advice** Nearside Front headlight lens fading**MOT #8** 2016-04-20 07:38**MOT test number** 738157062517**Result** ✓ Passed**Advice** Both rear tyres misshapped**MOT #7** 2015-04-22 08:47**MOT test number** 336332215123**Result** ✓ Passed**MOT #6** 2014-05-03 09:52**MOT test number** 639843224115**Result** ✓ Passed**MOT #5** 2013-05-31 15:06**MOT test number** 267791553106**Result** ✓ Passed**Advice** Offside Headlamp has a product on the light source but not seriously reducing light output (1.7.5a)**MOT #4** 2012-05-15 09:24**MOT test number** 215756532451**Result** ✓ Passed**Advice** Offside Front Headlamp damaged but light output not reduced (1.7.5a)



MOT #3	2011-05-03 12:25
MOT test number	859703421162
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2010-05-10 13:35
MOT test number	270140430425
Result	✓ Passed

MOT #1	2009-05-11 12:06
MOT test number	884081839155
Result	✓ Passed



Tax & MOT check

✓

Taxed

Tax due:
1 March 2025

✓

MOT

Expires:
19 March 2025

Tax status	Valid until 1 March
Days left	307
MOT expiry date	19 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-01-01
Current registration	
Plate since	2019-01-01

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-05-17
Last registration	2024-03-13
Complete history	See info



Registration #1	2006-05-17	27 mi
Registration #2	2009-05-11	29.207 mi
Registration #3	2010-05-10	35.986 mi
Registration #4	2011-05-03	42.157 mi
Registration #5	2012-05-15	46.072 mi
Registration #6	2013-05-31	51.929 mi
Registration #7	2014-05-03	56.094 mi
Registration #8	2015-04-22	60.558 mi
Registration #9	2016-04-20	64.772 mi
Registration #10	2017-04-06	69.291 mi
Registration #11	2018-05-20	75.277 mi
Registration #12	2019-05-20	81.277 mi
Registration #13	2020-05-20	87.277 mi
Registration #14	2021-05-20	93.277 mi
Registration #15	2022-05-20	99.277 mi
Registration #16	2023-05-20	105.277 mi
Registration #17	2024-03-13	111.277 mi
Registration #18		
Registration #19		
Registration #20		

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1760 mm
Height	1445 mm
Length	4665 mm
Wheel base	2670 mm
Kerb weight	1436 kg
Max. allowed weight	1930 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Engine number	K24A64003830