



TOYOTA




report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VVTI T3
Colour	Black
Year of manufacture	2006
Top speed	109 mph
0 - 60 mph	11.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	109 BHP
Max. torque	150 Nm at 3.800 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.8 mpg
CO2 emission	190 g/km
CO2 label	J





## Internet history

### Entry 2


Date	2022-02-26
Pictures	16
Listing price	<a href="#">View report</a>



source: yesauto.com

### Entry 1

Date	2022-02-23
Pictures	5
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-03-11
MOT pass rate	84 %
MOT passed	16
Failed MOT tests	3
Total advice items	27
Total items failed	3

MOT #19	2024-03-12 12:10
MOT test number	473289097900
Result	✓ Passed
Next expiry date	2025-03-11

MOT #18	2023-03-09 16:06
MOT test number	287362585185
Result	✓ Passed
Advice	Slight underbody corrosion

MOT #17	2022-03-04 14:08
MOT test number	621875483071
Result	✓ Passed

MOT #16	2022-03-03 16:27
MOT test number	717528536963
Result	✗ Failed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Nearside Rear Service brake excessively binding (1.2.1 (f))

**MOT #15**

2021-06-10 09:23

**MOT test number**

735855828964

**Result**

✓ Passed

- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**MOT #14**

2020-06-25 10:18

**MOT test number**

705053222684

**Result**

✓ Passed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Advise front lower arms corroded
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**MOT #13**

2019-06-24 09:20

**MOT test number**

472577899149

**Result**

✓ Passed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #12** 2018-06-06 08:25**MOT test number** 106633306066**Result** ✓ Passed

**Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**MOT #11** 2017-06-12 16:07**MOT test number** 245410521066**Result** ✓ Passed**MOT #10** 2017-06-12 08:31**MOT test number** 606600755595**Result** ✗ Failed

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure 195/60r15 (4.1.D.1b)

**MOT #9** 2016-06-09 08:21**MOT test number** 740850224424**Result** ✓ Passed

**Advice** Advise rear tyres tread starting to lift

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #8** 2015-06-23 09:22**MOT test number** 179174475100**Result** ✓ Passed

**MOT #7** 2014-06-30 15:40**MOT test number** 217281784181**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-06-30 09:17**MOT test number** 226091484440**Result** ✗ Failed**Notice** Advise n/s/f fog light not working**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Front brake application uneven (3.7.B.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-08-08 11:39**MOT test number** 916450323296**Result** ✓ Passed**MOT #4** 2012-09-03 09:45**MOT test number** 258707742271**Result** ✓ Passed**MOT #3** 2011-08-30 10:44**MOT test number** 128782441243**Result** ✓ Passed**MOT #2** 2010-08-31 15:43**MOT test number** 831773840214**Result** ✓ Passed



MOT #1	2009-09-07 11:33
MOT test number	160810259248
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
11 March 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	11 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-01-01
Current registration	
Plate since	2019-01-01

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-09-15
Last registration	2024-03-12
Complete history	<a href="#">See info</a>



Registration #1	2006-09-15	16 mi
Registration #2	2009-09-07	25.209 mi
Registration #3	2010-08-31	32.272 mi
Registration #4	2011-08-30	39.603 mi
Registration #5	2012-09-03	45.221 mi
Registration #6	2013-08-08	50.309 mi
Registration #7	2014-06-30	55.288 mi
Registration #8	2014-06-30	55.288 mi
Registration #9	2015-06-23	61.369 mi
Registration #10	2016-06-09	66.197 mi
Registration #11	2017-06-12	69.340 mi
Registration #12	2018-06-12	75.277 mi
Registration #13	2019-06-12	81.214 mi
Registration #14	2020-06-12	87.151 mi
Registration #15	2021-06-12	93.088 mi
Registration #16	2022-06-12	99.025 mi
Registration #17	2023-06-12	104.962 mi
Registration #18	2024-03-12	110.899 mi
Registration #19	2024-03-12	110.899 mi
Registration #20	2024-03-12	110.899 mi
Registration #21	2024-03-12	110.899 mi
Registration #22	2024-03-12	110.899 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1250 kg
Max. allowed weight	1670 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	3ZZU805903