



report date: 2024-03-28

General information

Make	FORD
Model	FOCUS C-MAX ZETEC
Colour	Blue
Year of manufacture	-
Top speed	107 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	145 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT #15	2020-06-12 14:03
MOT test number	735358536344
Result	✓ Passed
Next expiry date	2021-06-11
Advice	Rear Exhaust mounting defective (6.1.2 (a))
Advice	Central tin shield covering fuel tank lose but not insucure

MOT #14	2020-05-27 15:52
MOT test number	254357533036
Result	✗ Failed
Advice	Rear Exhaust mounting defective (6.1.2 (a))
Advice	Central tin shield covering fuel tank lose, but nut insecure
Fail	Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Offside Front Drive shaft bearing excessively worn (6.1.7 (b) (i))
Fail	Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #13	2019-05-29 15:00
MOT test number	560139598662
Result	✓ Passed
Advice	Power steering component has slight seepage from a component (2.1.5 (a))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #12	2018-03-27 12:05
MOT test number	842945217914
Result	✓ Passed

MOT #11	2017-03-31 12:30
MOT test number	125393587711
Result	✓ Passed

**MOT #10** 2016-02-20 10:29**MOT test number** 302889967664**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2015-03-07 09:35**MOT test number** 108736865419**Result** ✓ Passed**MOT #8** 2014-03-08 09:31**MOT test number** 879997364035**Result** ✓ Passed**MOT #7** 2013-03-02 09:45**MOT test number** 527591963063**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #6** 2012-03-14 15:43**MOT test number** 687324572086**Result** ✓ Passed**MOT #5** 2010-12-17 17:47**MOT test number** 451451450483**Result** ✓ Passed

**MOT #4** 2010-12-17 11:40**MOT test number** 444781750332**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside Front Brake hose kinked (3.6.B.4b)**MOT #3** 2009-07-13 11:44**MOT test number** 182744499167**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Airbag light staying on**MOT #2** 2008-06-09 16:33**MOT test number** 882141268109**Result** ✓ Passed**Notice** Air bag light staying on**MOT #1** 2008-06-09 12:03**MOT test number** 170441268148**Result** ✗ Failed**Fail** Nearside rear brake application uneven (3.7.B.2)**Fail** Front brake application uneven (3.7.B.2)**Fail** Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Air bag light staying on



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2005-02-18
Last registration	2020-06-12
Complete history	See info



Registration #1	2005-02-18	25 mi
Registration #2	2008-06-09	30.792 mi
Registration #3	2008-06-09	30.792 mi
Registration #4	2009-07-13	37.586 mi
Registration #5	2010-12-17	44.546 mi
Registration #6	2010-12-17	44.546 mi
Registration #7	2012-03-14	46.985 mi
Registration #8	2013-03-02	48.343 mi
Registration #9	2014-03-08	52.268 mi
Registration #10	2015-03-02	55.217 mi
Registration #11	2015-03-02	55.217 mi
Registration #12	2015-03-02	55.217 mi
Registration #13	2015-03-02	55.217 mi
Registration #14	2015-03-02	55.217 mi
Registration #15	2015-03-02	55.217 mi
Registration #16	2015-03-02	55.217 mi
Registration #17	2015-03-02	55.217 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1783 mm
Height	1558 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1371 kg
Max. allowed weight	1855 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	5U39201