



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 1700
Colour	Silver
Year of manufacture	2008
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	125 Nm at 4.000 rpm
Engine capacity	1.364 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-11-04
Pictures	10
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-26
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	16
Total items failed	13

MOT #15	2023-11-27 11:14
MOT test number	916902834521
Result	✓ Passed
Next expiry date	2024-11-26

MOT #14	2022-11-14 10:39
MOT test number	880053920726
Result	✓ Passed

MOT #13	2021-10-14 15:34
MOT test number	705165026644
Result	✓ Passed

MOT #12	2019-01-08 17:24
MOT test number	132629413508
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #11**

2019-01-02 12:36

**MOT test number**

841376883350

**Result**

✗ Failed

- Fail** Offside Headlamp aim too low (4.1.2 (a))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Fail** Nearside Headlamp aim too low (4.1.2 (a))
- Fail** Offside Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**MOT #10**

2018-01-05 14:34

**MOT test number**

103231775621

**Result**

✓ Passed

- Advice** Offside front tyre on limit inner edge
- Advice** Offside rear tyre on limit edge

**MOT #9**

2017-01-09 10:23

**MOT test number**

532265978229

**Result**

✓ Passed

**MOT #8**

2016-01-09 14:53

**MOT test number**

467579031099

**Result**

✓ Passed

**MOT #7** 2016-01-08 16:54**MOT test number** 296646500543**Result** ✗ Failed**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #6** 2014-11-26 15:49**MOT test number** 359060934313**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #5** 2013-11-12 16:53**MOT test number** 876686813395**Result** ✓ Passed**Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #4** 2013-11-11 10:16**MOT test number** 798105513340**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #3** 2012-12-05 13:35**MOT test number** 835780042340**Result** ✓ Passed**MOT #2** 2012-11-16 11:56**MOT test number** 606131022317**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Pass with rectification** Offside Headlamp aim too high (1.8)**Pass with rectification** Nearside Headlamp aim too high (1.8)**MOT #1** 2011-11-03 11:44**MOT test number** 447717601407**Result** ✓ Passed**Notice** Nail in n/s/r tyre**Advice** Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
26 November 2024

Tax status		Valid until 1 April
Days left		336
MOT expiry date		26 November 2024
Full MOT history		<a href="#">See MOT history</a>



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>EK580CG</b>
Plate since	2024-03-29
Current registration	 <b>EK580CG</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-11-18
Last registration	2023-11-27
Complete history	<a href="#">See info</a>



Registration #1	2008-11-18	6 mi
Registration #2	2011-11-03	36.807 mi
Registration #3	2012-11-16	60.085 mi
Registration #4	2012-12-05	61.093 mi
Registration #5	2013-11-11	74.337 mi
Registration #6	2013-11-12	74.337 mi
Registration #7	2014-11-26	84.313 mi
Registration #8	2016-01-08	98.338 mi
Registration #9	2016-01-09	98.338 mi
Registration #10	2016-01-09	98.338 mi
Registration #11	2016-01-09	98.338 mi
Registration #12	2016-01-09	98.338 mi
Registration #13	2016-01-09	98.338 mi
Registration #14	2016-01-09	98.338 mi
Registration #15	2016-01-09	98.338 mi
Registration #16	2016-01-09	98.338 mi
Registration #17	2016-01-09	98.338 mi

More info >



Dimensions & weight

Width	1892 mm
Height	1801 mm
Length	4323 mm
Kerb weight	1122 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	2
Engine number	19RC2822