



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	SCIROCCO GT
Colour	Blue
Year of manufacture	2008
Top speed	145 mph
0 - 60 mph	7.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	200 BHP
Max. torque	280 Nm at 1.700 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	47.9 mpg
Consumption combined	37.2 mpg
CO2 emission	179 g/km
CO2 label	I





## Internet history

### Entry 6


Date	2022-01-09
Pictures	9
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 5

Date	2021-10-30
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)


### Entry 4

Date	2021-10-29
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 3

Date	2021-07-26
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 2

Date	2021-07-25
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date	2021-06-23
Pictures	0
Listing price	<a href="#">View report</a>

source: [cargurus.co.uk](https://www.cargurus.co.uk)



## MOT history

MOT expiry date	2024-10-03
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	28
Total items failed	10

MOT #18	2023-10-04 09:31
MOT test number	468724762899
Result	✓ Passed
Next expiry date	2024-10-03
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #17	2022-09-22 15:55
MOT test number	809335105941
Result	✓ Passed
Advice	Offside Rear tyre is perishing
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #16	2021-07-08 11:26
MOT test number	671112584197
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2020-11-23 16:20
MOT test number	828574065942
Result	✓ Passed

**MOT #14** 2020-11-20 15:09**MOT test number** 842270494406**Result** ✗ Failed**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** N/s/r brake disc appears to have got hot.**MOT #13** 2019-11-21 14:58**MOT test number** 300272284017**Result** ✓ Passed**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge Wearing on inside edge (5.2.3 (e))**Advice** Offside Rear Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Door mirror glass missing**MOT #12** 2019-11-18 11:08**MOT test number** 853004100258**Result** ✗ Failed**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Windscreen wiper does not clear the windscreen effectively Both sides. (3.4 (b) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #11** 2018-11-20 15:34**MOT test number** 409720350510**Result** ✓ Passed

**MOT #10**

2017-11-14 14:08

**MOT test number**

472047917560

**Result**

✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened Got a lip (3.5.1i)
- Advice** Offside Front Outer Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened Got a lip (3.5.1i)
- Advice** Nearside Front Outer Brake pad(s) wearing thin (3.5.1g)

**MOT #9**

2017-11-14 09:47

**MOT test number**

123156011536

**Result**

✗ Failed

- Advice** Offside Front Outer Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened Got a lip (3.5.1i)
- Advice** Nearside Front Outer Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened Got a lip (3.5.1i)

**MOT #8**

2016-11-11 12:28

**MOT test number**

264974842406

**Result**

✓ Passed

- Advice** Nearside Rear Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)

**MOT #7** 2015-11-03 15:30**MOT test number** 620628959458**Result** ✓ Passed**MOT #6** 2014-11-07 11:43**MOT test number** 476291914337**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2014-11-05 14:22**MOT test number** 555469704359**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2013-10-28 10:24**MOT test number** 476561003442**Result** ✓ Passed**MOT #3** 2012-10-29 17:26**MOT test number** 917613802339**Result** ✓ Passed



MOT #2	2011-12-13 13:29
MOT test number	696097241365
Result	✓ Passed
<div>Notice</div> Damage to nearside front tyre outer sidewall	

MOT #1	2011-01-07 15:59
MOT test number	277247001093
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
3 October 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	3 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2008-11-03
Last registration	2023-10-04
Complete history	<a href="#">See info</a>



Registration #1	2008-11-03	12 mi
Registration #2	2011-01-07	16.493 mi
Registration #3	2011-12-13	24.804 mi
Registration #4	2012-10-29	32.865 mi
Registration #5	2013-10-28	43.274 mi
Registration #6	2014-11-05	50.378 mi
Registration #7	2014-11-07	50.390 mi
Registration #8	2015-11-03	65.503 mi
Registration #9	2016-11-11	73.935 mi
Registration #10	2017-11-14	78.485 mi
Registration #11	2017-11-14	78.485 mi
Registration #12	2018-11-20	84.890 mi
Registration #13	2019-11-18	90.837 mi
Registration #14	2020-05-20	95.377 mi
Registration #15	2020-05-20	95.377 mi
Registration #16	2020-05-20	95.377 mi
Registration #17	2020-05-20	95.377 mi
Registration #18	2020-05-20	95.377 mi
Registration #19	2020-05-20	95.377 mi
Registration #20	2020-05-20	95.377 mi
Registration #21	2020-05-20	95.377 mi
Registration #22	2020-05-20	95.377 mi
Registration #23	2020-05-20	95.377 mi
Registration #24	2020-05-20	95.377 mi
Registration #25	2020-05-20	95.377 mi



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1810 mm
Height	1404 mm
Length	4256 mm
Wheel base	2578 mm
Kerb weight	1318 kg
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	CAW 019753