



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM BLUE DRIVE
Colour	Black
Year of manufacture	2016
Top speed	126 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	197 BHP
Max. torque	440 Nm at 2.750 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G






Internet history

Entry 3

Date	2024-04-12
Pictures	51
Listing price	View report



source: cargurus.co.uk

Entry 2

Date	2022-01-14
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2022-01-13
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-25
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	16
Total items failed	0

MOT #6	2024-02-26 14:42
MOT test number	812952983908
Result	✓ Passed
Next expiry date	2025-02-25
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))
Advice	Offside Front Tyre slightly damaged outer side wall (5.2.3 (d) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))
Advice	Nearside Front Tyre slightly damaged outer side wall (5.2.3 (d) (ii))

MOT #5	2023-02-02 09:08
MOT test number	681017950122
Result	✓ Passed
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #4	2021-09-21 10:35
MOT test number	446859952660
Result	✓ Passed

**MOT #3** 2020-09-10 13:23**MOT test number** 948130064209**Result** ✓ Passed

- Advice** Nearside Body component slightly loose Side step broken (6.2.1 (a) (i))
- Advice** Nearside Front Nail in tyre
- Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2020-09-09 12:28**MOT test number** 539620895647**Result** ✗ Failed

- Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Electronic parking brake warning indicates a malfunction (1.1.6 (e))
- MAJOR** Brake performance not tested (1.2.1 (g))
- Advice** Nearside Front Nail in tyre
- MAJOR** Electronic parking brake control defective so that it cannot be satisfactorily operated (1.1.6 (d))
- Advice** Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Body component slightly loose Side step broken (6.2.1 (a) (i))

MOT #1 2019-09-20 14:19**MOT test number** 570971925559**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
15 March 2024

✓

MOT

Expires:
25 February 2025

Tax status	Expired at 15 March 2024
Days left	45 days too late
MOT expiry date	25 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-09-30
Last registration	2024-02-26
Complete history	See info



Registration #1	2016-09-30	15 mi
Registration #2	2019-09-20	24.370 mi
Registration #3	2020-09-09	28.845 mi
Registration #4	2020-09-10	28.846 mi
Registration #5	2021-09-21	34.184 mi
Registration #6	2022-09-20	35.377 mi
Registration #7	2023-09-20	35.377 mi
Registration #8	2024-02-26	35.377 mi
Registration #9	2024-02-26	35.377 mi
Registration #10	2024-02-26	35.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	89%
Pedestrian	71%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1880 mm
Height	1675 mm
Length	4700 mm
Wheel base	2700 mm
Kerb weight	1977 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	D4HBGU494349