



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN S TDI
Colour	Black
Year of manufacture	2011
Top speed	114 mph
0 - 100 km/h	12.8 seconds
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	77 kW / 105 HP / 106 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	6.3 mpg
CO2 emission	134 g/km
CO2 label	E






Internet history

Entry 1

Date	2022-03-26
Pictures	3
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-08
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	10
Total items failed	4

MOT #12	2023-06-09 12:35
MOT test number	963901937027
Result	✓ Passed
Next expiry date	2024-06-08
Advice	Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #11	2022-04-28 13:31
MOT test number	280026328368
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing cracking on inner edge (5.2.3 (d) (ii))

MOT #10	2021-02-17 18:05
MOT test number	874134573965
Result	✓ Passed

**MOT #9** 2021-02-17 15:27**MOT test number** 348187906808**Result** ✗ Failed**Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2020-02-18 17:41**MOT test number** 803006247756**Result** ✓ Passed**MOT #7** 2020-02-18 14:25**MOT test number** 850501510708**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #6** 2019-02-18 12:12**MOT test number** 774452625970**Result** ✓ Passed**Advice** Front Upper Anti-roll bar linkage damaged but not seriously weakened both sides (5.3.3 (b) (i))**MOT #5** 2017-11-08 13:37**MOT test number** 698068004632**Result** ✓ Passed**Advice** Oil leak**Advice** Rear subframe slightly corroded



MOT #4	2016-06-17 13:30
---------------	------------------

MOT test number	504817247057
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2015-06-10 14:10
---------------	------------------

MOT test number	717131465133
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	Under-trays fitted obscuring some underside components
---------------	--

Notice	Engine covers fitted obscuring some components in the engine bay
---------------	--

MOT #2	2014-09-12 16:03
---------------	------------------

MOT test number	428615554284
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2014-05-13 13:56
---------------	------------------

MOT test number	428843934135
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	Rear tyres wearing on inner edges
---------------	-----------------------------------



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
8 June 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	8 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 GV11BWK
Plate since	2019-06-29
Current registration	 GV11BWK
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-06-10
Last registration	2023-06-09
Complete history	See info



Registration #1	2011-06-10	16 mi
Registration #2	2014-05-13	27.907 mi
Registration #3	2014-09-12	32.203 mi
Registration #4	2015-06-10	39.781 mi
Registration #5	2016-06-17	52.638 mi
Registration #6	2017-11-08	62.917 mi
Registration #7	2019-02-18	72.492 mi
Registration #8	2019-05-20	75.277 mi
Registration #9	2019-05-20	75.277 mi
Registration #10	2019-05-20	75.277 mi
Registration #11	2019-05-20	75.277 mi
Registration #12	2019-05-20	75.277 mi
Registration #13	2019-05-20	75.277 mi
Registration #14	2019-05-20	75.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1634 mm
Length	4397 mm
Wheel base	2678 mm
Kerb weight	1539 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
-----------------	---

Engine number	CAY 586764
---------------	------------