



report date: 2024-03-28

General information

Make	FORD
Model	FIESTA STYLE PLUS TDCI
Colour	Blue
Year of manufacture	2010
Top speed	101 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	67.3 mpg
CO2 emission	110 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-06-04
Pictures	12
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-20
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	41
Total items failed	13

MOT #17	2023-06-28 14:58
MOT test number	963498788138
Result	✓ Passed
Next expiry date	2024-07-20
Advice	Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
Advice	Play in steering rack inner joint(s)
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #16**

2023-06-28 10:15

MOT test number

744076029849

Result**✗ Failed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
- Advice** Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Play in steering rack inner joint(s)
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #15

2022-07-21 11:12

MOT test number

949325976291

Result**✓ Passed****MOT #14**

2021-06-21 14:14

MOT test number

428479461292

Result**✓ Passed**

- Advice** Outer skin rear silencer corroded

**MOT #13**

2020-06-22 15:33

MOT test number

928444708921

Result

✓ Passed

- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Exhaust silencer outer skin deteriorating
- Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

MOT #12

2020-06-08 16:08

MOT test number

668210462719

Result

✗ Failed

- Fail** Exhaust emissions exceed manufacturer's specified limit 1.1 (8.2.2.2 (a))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Exhaust silencer outer skin deteriorating
- Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

**MOT #11** 2019-06-12 06:33**MOT test number** 236780683416**Result** ✓ Passed

- Advice** Exhaust rear silencer deteriorated.
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Oil leak, but not excessive engine & gearbox (8.4.1 (a) (i))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #10 2019-06-12 06:33**MOT test number** 549708807408**Result** ✗ Failed

- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Oil leak, but not excessive engine & gearbox (8.4.1 (a) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Exhaust rear silencer deteriorated.
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #9 2018-06-11 08:24**MOT test number** 998753773086**Result** ✓ Passed

**MOT #8** 2018-05-25 06:55**MOT test number** 457125675602**Result** ✗ Failed**Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Engine mounting damaged or deteriorated resulting in excessive movement (6.1.8 (a) (i))**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #7** 2017-06-03 06:55**MOT test number** 472219690107**Result** ✓ Passed**Advice** Exhaust rear silencer corroded**Advice** O/S/F tyre scrubbed off on inner edge**Advice** Brake pedal rubber split**MOT #6** 2016-06-21 13:28**MOT test number** 688324070495**Result** ✓ Passed**Advice** Rear fog lamp damaged, but still visible from a reasonable distance (1.3.2d)**Advice** O/f tyre scrubbing inner edge**MOT #5** 2015-06-16 16:19**MOT test number** 989467065154**Result** ✓ Passed



MOT #4	2015-06-16 16:19
MOT test number	286497665441
Result	✗ Failed
Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)

MOT #3	2014-06-04 11:59
MOT test number	108505554119
Result	✓ Passed

MOT #2	2014-06-03 14:54
MOT test number	295444254485
Result	✗ Failed
Fail	Offside front brake binding (3.7.B.1)
Fail	Nearside Track rod end ball joint has excessive play (2.2.B.1f)
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #1	2013-05-29 09:05
MOT test number	695299443117
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
20 July 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	20 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-06-25
Last registration	2023-06-28
Complete history	See info



Registration #1	2010-06-25	22 mi
Registration #2	2013-05-29	37.207 mi
Registration #3	2014-06-03	51.619 mi
Registration #4	2014-06-04	51.619 mi
Registration #5	2015-06-16	64.223 mi
Registration #6	2016-06-21	76.677 mi
Registration #7	2017-06-03	84.980 mi
Registration #8	2018-05-25	92.469 mi
Registration #9	2018-06-11	92.476 mi
Registration #10	2019-06-28	92.476 mi
Registration #11	2019-06-28	92.476 mi
Registration #12	2019-06-28	92.476 mi
Registration #13	2019-06-28	92.476 mi
Registration #14	2019-06-28	92.476 mi
Registration #15	2019-06-28	92.476 mi
Registration #16	2019-06-28	92.476 mi
Registration #17	2019-06-28	92.476 mi
Registration #18	2019-06-28	92.476 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1973 mm
Height	1481 mm
Length	3950 mm
Kerb weight	1141 kg
Max. allowed weight	1535 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2

Engine number

9R21853