



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV-4 VVTI GX
Colour	Blue
Year of manufacture	2003
Top speed	112 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	146 BHP
Max. torque	193 Nm at 4.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.8 mpg
Consumption extra urban	38.7 mpg
Consumption combined	32.1 mpg
CO2 emission	211 g/km
CO2 label	K







Internet history

Entry 1

Date	2021-07-23
Pictures	15
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT expiry date</b>	2022-05-16
<b>MOT pass rate</b>	83 %
<b>MOT passed</b>	15
<b>Failed MOT tests</b>	3
<b>Total advice items</b>	26
<b>Total items failed</b>	3

**MOT #18** 2021-05-17 14:17**MOT test number** 816261980135**Result** Passed**Next expiry date** 2022-05-16

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Under body seal added under vehicle
- Advice** Central Exhaust has a minor leak of exhaust gases system corroded (6.1.2 (a))

**MOT #17** 2020-06-18 15:12**MOT test number** 444530882318**Result** Passed

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #16**

2018-11-30 12:53

**MOT test number**

935895522141

**Result**

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Items removed from driver's view prior to test

**MOT #15**

2018-11-30 12:53

**MOT test number**

960935092441

**Result**

✗ Failed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))
- Advice** Items removed from driver's view prior to test
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #14**

2017-11-03 09:02

**MOT test number**

290077166981

**Result**

✓ Passed

- Advice** Offside Front Brake pipe slightly corroded to rear (3.6.B.2c)
- Advice** Nearside Front Brake pipe slightly corroded to rear (3.6.B.2c)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #13** 2016-11-07 09:13**MOT test number** 674560494252**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Brake pipe slightly corroded to rear hose (3.6.B.2c)
- Advice** Nearside Front Brake pipe slightly corroded to rear hose (3.6.B.2c)

**MOT #12** 2015-11-09 09:08**MOT test number** 981951552650**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #11** 2014-11-03 15:41**MOT test number** 658237704309**Result** ✓ Passed**MOT #10** 2014-11-03 09:29**MOT test number** 278527804399**Result** ✗ Failed

- Fail** Offside Rear coil spring broken (2.4.C.1a)

**MOT #9** 2013-11-05 11:38**MOT test number** 978709003304**Result** ✓ Passed**MOT #8** 2012-11-06 09:09**MOT test number** 966301412358**Result** ✓ Passed

**MOT #7** 2011-11-07 09:30**MOT test number** 437091811400**Result** ✓ Passed**MOT #6** 2010-11-09 09:30**MOT test number** 580383310357**Result** ✓ Passed**MOT #5** 2010-11-09 09:30**MOT test number** 873393310393**Result** ✗ Failed

**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #4** 2009-10-27 09:42**MOT test number** 973100709329**Result** ✓ Passed

**Notice** Front pads 50%

**MOT #3** 2008-10-28 09:31**MOT test number** 622482108300**Result** ✓ Passed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #2** 2007-11-09 09:39**MOT test number** 111693417399**Result** ✓ Passed



MOT #1	2006-11-02 09:06
MOT test number	350046906320
Result	✓ Passed



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2003-11-15
Last registration	2021-05-17
Complete history	<a href="#">See info</a>



Registration #1	2003-11-15	13 mi
Registration #2	2006-11-02	16.409 mi
Registration #3	2007-11-09	22.955 mi
Registration #4	2008-10-28	28.995 mi
Registration #5	2009-10-27	34.396 mi
Registration #6	2010-11-09	40.161 mi
Registration #7	2011-11-07	45.416 mi
Registration #8	2012-11-06	50.686 mi
Registration #9	2013-11-05	54.789 mi
Registration #10	2014-11-03	60.078 mi
Registration #11	2015-11-02	65.377 mi
Registration #12	2016-11-01	70.676 mi
Registration #13	2017-10-31	75.975 mi
Registration #14	2018-10-30	81.274 mi
Registration #15	2019-10-29	86.573 mi
Registration #16	2020-10-28	91.872 mi
Registration #17	2021-05-17	97.171 mi
Registration #18		
Registration #19		

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1785 mm
Height	1710 mm
Length	4260 mm
Wheel base	2490 mm
Kerb weight	1385 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	1AZ1012713