



report date: 2024-03-29

General information

Make	FIAT
Model	SCUDO COMFORT SWB P/V 120 MULTIJET
Colour	Black
Year of manufacture	2010
Top speed	99 mph
0 - 60 mph	13.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	300 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel





MOT history

MOT expiry date	2021-07-22
MOT pass rate	57 %
MOT passed	8
Failed MOT tests	6
Total advice items	55
Total items failed	14

MOT #142020-07-10 10:54

MOT test number758723486581

Result✓ Passed

Next expiry date2021-07-22

- Advice

Nearside Front Tyre worn close to legal limit/worn on edge on outer edge (5.2.3 (e))
- Minor

Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Minor

Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Minor

Nearside Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice

Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

**MOT #13**

2020-07-10 10:54

MOT test number

133727708620

Result**✗ Failed**

- Advice** Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Pass with rectification** Rear Exhaust system insecure (6.1.2 (a))
- Pass with rectification** Rear Tyre tread depth below requirements of 1.6mm both (5.2.3 (e))
- Minor** Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge on outer edge (5.2.3 (e))
- Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))

MOT #12

2019-07-12 11:44

MOT test number

505077046343

Result**✓ Passed**

- Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #11**

2018-07-09 14:59

MOT test number

104721253650

Result

✓ Passed

Minor

Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #10

2018-07-09 11:01

MOT test number

339488216828

Result

✗ Failed

Minor

Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MAJOR

Offside Rear Exhaust system insecure (6.1.2 (a))

Advice

Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

MOT #9

2017-07-12 14:33

MOT test number

128131761822

Result

✓ Passed

Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice

Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

Advice

Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Advice

Nearside Anti-roll bar has slight play in a pin/bush (2.4.G.2)

Advice

Oil leak

Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice

Nearside Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Advice

Offside Anti-roll bar has slight play in a pin/bush (2.4.G.2)



MOT #8

2017-07-12 12:19

MOT test number

576020329697

Result

✗ Failed

- Advice

Oil leak
- Advice

Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail

Offside Stop lamp not working (1.2.1b)
- Advice

Nearside Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice

Offside Anti-roll bar has slight play in a pin/bush (2.4.G.2)
- Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail

Offside Front position lamp(s) not working (1.1.A.3b)
- Advice

Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Fail

Offside Registration plate lamp not working (1.1.C.1d)
- Advice

Nearside Anti-roll bar has slight play in a pin/bush (2.4.G.2)



MOT #7 2016-07-19 14:57

MOT test number 176541642264

Result ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Oil leak
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Offside Rear Nail in tyre
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #6**

2016-07-19 09:26

MOT test number

930564824436

Result**✗ Failed****Advice** Oil leak**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Nail in tyre**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Windscreen wiper blade insecure (8.2.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Centre Stop lamp not working (1.2.1b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Windscreen wiper blade insecure (8.2.2)**MOT #5**

2015-07-21 16:06

MOT test number

727362405213

Result**✓ Passed****MOT #4**

2015-07-21 10:27

MOT test number

729322305261

Result**✗ Failed****Fail** Nearside Front Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)



MOT #3	2014-07-16 14:41
MOT test number	789927394178
Result	✓ Passed

MOT #2	2014-07-16 14:41
MOT test number	155067494166
Result	✗ Failed
Pass with rectification	Offside Headlamp aim too high (1.8)
Pass with rectification	Nearside Headlamp aim too high (1.8)

MOT #1	2013-07-23 13:35
MOT test number	579864403279
Result	✓ Passed
Notice	N/s/f tyre has damage to sidewall



Tax & MOT check

✕
Untaxed

Tax expired:
19 November 2020

✕
MOT

Expired:
22 July 2021

Tax status

Expired at 19 November 2020

Days left

1257 days too late

MOT expiry date

22 July 2021

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-03-11
Last registration	2020-07-10
Complete history	See info



Registration #1	2010-03-11	15 mi
Registration #2	2013-07-23	43.368 mi
Registration #3	2014-07-16	55.238 mi
Registration #4	2015-07-21	68.729 mi
Registration #5	2015-07-21	68.729 mi
Registration #6	2016-07-19	84.322 mi
Registration #7	2016-07-19	84.322 mi
Registration #8	2016-07-19	84.322 mi
Registration #9	2016-07-19	84.322 mi
Registration #10	2016-07-19	84.322 mi
Registration #11	2016-07-19	84.322 mi
Registration #12	2016-07-19	84.322 mi
Registration #13	2016-07-19	84.322 mi
Registration #14	2016-07-19	84.322 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1895 mm
Height	1942 mm
Length	4805 mm
Kerb weight	1702 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	4025587