



report date: 2024-03-28

General information

|                     |                |
|---------------------|----------------|
| Make                | MINI           |
| Model               | MINI FIRST     |
| Colour              | Orange         |
| Year of manufacture | 2010           |
| Top speed           | 109 mph        |
| 0 - 60 mph          | 13.2 seconds   |
| Gearbox             | 6 speed Manual |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 75 BHP              |
| Max. torque             | 140 Nm at 2.500 rpm |
| Engine capacity         | 1.598 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 39.2 mpg            |
| Consumption extra urban | 64.2 mpg            |
| Consumption combined    | 52.3 mpg            |
| CO2 emission            | 127 g/km            |
| CO2 label               | D                   |





MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2025-02-15 |
| MOT pass rate      | 92 %       |
| MOT passed         | 11         |
| Failed MOT tests   | 1          |
| Total advice items | 18         |
| Total items failed | 8          |

|                  |                  |
|------------------|------------------|
| MOT #12          | 2024-01-24 13:38 |
| MOT test number  | 758036394207     |
| Result           | ✓ Passed         |
| Next expiry date | 2025-02-15       |

|                 |                  |
|-----------------|------------------|
| MOT #11         | 2023-02-13 12:43 |
| MOT test number | 713715273473     |
| Result          | ✓ Passed         |

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge VERY LOW ON TREAD ! (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement REAR MOST MAIN BUSHES SOFT (FRONT OF CAR) (5.3.4 (a) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing WALL IS CRACKING ! (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge getting low on tread ! (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement REAR MOST MAIN BUSHES SOFT (FRONT OF CAR) (5.3.4 (a) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing WALL OF TYRE IS CRACKING ! (5.2.3 (d) (ii))

**MOT #10** 2022-02-16 18:34**MOT test number** 386318343744**Result** ✓ Passed**Advice** Front Exhaust has a minor leak of exhaust gases slight leak from flexi-joint (6.1.2 (a))**Minor** Offside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))**Advice** Brake hose has slight corrosion to ferrule front & rear (1.1.12 (f) (i))**Advice** Front Tyre slightly damaged/cracking or perishing nearside & offside (5.2.3 (d) (ii))**Advice** Sub-frame corroded but not seriously weakened front & rear (5.3.3 (b) (i))**MOT #9** 2021-01-28 11:09**MOT test number** 770589894106**Result** ✓ Passed**MOT #8** 2020-02-03 14:33**MOT test number** 405657515208**Result** ✓ Passed**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #7** 2019-02-01 09:22**MOT test number** 240824041407**Result** ✓ Passed**MOT #6** 2018-02-10 10:28**MOT test number** 275709906425**Result** ✓ Passed

**MOT #5** 2018-02-05 12:56**MOT test number** 881760681876**Result** ✗ Failed

- Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Fail** Front brake excessively fluctuating (3.7.B.3)
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Fail** Front brake disc in such a condition that it is seriously weakened (3.5.1i)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #4** 2016-10-07 08:21**MOT test number** 187466889236**Result** ✓ Passed

- Advice** All tyres cracking on tread
- Advice** Nearside Rear Nail in tyre

**MOT #3** 2015-10-09 09:19**MOT test number** 852347130281**Result** ✓ Passed**MOT #2** 2014-10-10 14:31**MOT test number** 528613084241**Result** ✓ Passed



|                 |                  |
|-----------------|------------------|
| MOT #1          | 2013-10-14 12:42 |
| MOT test number | 499967183268     |
| Result          | ✓ Passed         |



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
15 February 2025

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 September         |
| <b>Days left</b>        | 125                             |
| <b>MOT expiry date</b>  | 15 February 2025                |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |            |
|--|------------|
| <b>Vehicle class</b>                           | 48         |
| <b>Band</b>                                    | D          |
| <b>Single payment (12 months)</b>              | £ 150,00,- |
| <b>Single six month payment</b>                | £ 82,50,-  |
| <b>Total payable by 12 monthly instalments</b> | £ 157,50,- |



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

|          |  |
|----------|--|
| Damage 1 |  |
| Date     |  |
| Category |  |
| Type     |  |
| Damage 2 |  |
| Date     |  |
| Category |  |
| Type     |  |



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this MINI had different number plates.

|                      |                |
|----------------------|----------------|
| Number of plates     | 1              |
| Current registration | <b>MT60KYH</b> |
| Plate since          | 2019-09-29     |
| Current registration | <b>MT60KYH</b> |
| Plate since          | 2019-09-29     |

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

|                   |          |          |
|-------------------|----------|----------|
| Finance company   | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type    | REDACTED | REDACTED |
| Agreement term    | REDACTED | REDACTED |
| Agreement number  | REDACTED | REDACTED |
| Contact info      | REDACTED | REDACTED |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 13                       |
| First mileage registration | 2010-12-23               |
| Last registration          | 2024-01-24               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2010-12-23 | 10 mi     |
| Registration #2  | 2013-10-14 | 12.358 mi |
| Registration #3  | 2014-10-10 | 15.135 mi |
| Registration #4  | 2015-10-09 | 18.905 mi |
| Registration #5  | 2016-10-07 | 26.773 mi |
| Registration #6  | 2018-02-05 | 29.328 mi |
| Registration #7  | 2018-02-10 | 29.370 mi |
| Registration #8  | 2019-05-20 | 35.277 mi |
| Registration #9  | 2019-05-20 | 35.277 mi |
| Registration #10 | 2019-05-20 | 35.277 mi |
| Registration #11 | 2019-05-20 | 35.277 mi |
| Registration #12 | 2019-05-20 | 35.277 mi |
| Registration #13 | 2019-05-20 | 35.277 mi |

More info >



Car features

The MINI factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1683 mm |
| Height              | 1407 mm |
| Length              | 3699 mm |
| Wheel base          | 2467 mm |
| Kerb weight         | 1060 kg |
| Max. allowed weight | 1510 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 40 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 3                     |
| Number of seats    | 4                     |

|                        |          |
|------------------------|----------|
| <b>Number of axles</b> | 2        |
| <b>Engine number</b>   | A406I693 |