



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 R-DESIGN
Colour	White
Year of manufacture	2011
Top speed	130 mph
0 - 60 mph	8.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.2 mpg
CO2 emission	177 g/km
CO2 label	I





Internet history

Entry 1

Date	2022-03-20
Pictures	20
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-13
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	31
Total items failed	6

MOT #14	2023-12-28 16:06
MOT test number	456085143185
Result	✓ Passed
Next expiry date	2025-01-13
Advice	Nearside Rear Brake pad(s) wearing thin [STRONG ADVISE] (1.1.13 (a) (ii))
Advice	Front Coil spring corroded both (5.3.1 (b) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both corroded (1.1.14 (a) (ii))
Minor	Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both corroded (1.1.14 (a) (ii))
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))

**MOT #13**

2023-12-28 13:28

MOT test number

146059284759

Result**✗ Failed**

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both corroded (1.1.14 (a) (ii))
- Advice** Front Coil spring corroded both (5.3.1 (b) (i))
- Advice** Nearside Rear Brake pad(s) wearing thin [STRONG ADVISE] (1.1.13 (a) (ii))
- Fail** Nearside Rear Bumper damaged and likely to cause injury when grazed or contacted (6.1.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both corroded (1.1.14 (a) (ii))
- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))
- Minor** Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

MOT #12

2023-01-07 11:55

MOT test number

978848544469

Result**✓ Passed**

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Coil spring corroded (5.3.1 (b) (i))
- Minor** Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #11**

2022-01-14 15:24

MOT test number

707499944087

Result

✓ Passed

- Advice** Rear Direction indicator slightly discoloured Both sides (4.4.3 (a))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Brake caliper slightly damp

MOT #10

2020-12-08 12:18

MOT test number

230911561862

Result

✓ Passed

- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge wearing inner edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing inner edge (5.2.3 (e))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

MOT #9

2020-12-08 11:29

MOT test number

950425982411

Result

✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing inner edge (5.2.3 (e))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge wearing inner edge (5.2.3 (e))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

**MOT #8** 2019-07-31 11:41**MOT test number** 765521784490**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2019-07-31 11:41**MOT test number** 795702971658**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp adversely affected by the operation of another lamp (4.2.3 (c))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2018-07-14 07:47**MOT test number** 389788744020**Result** ✓ Passed**MOT #5** 2017-08-11 10:29**MOT test number** 449777432355**Result** ✓ Passed**MOT #4** 2016-07-23 11:36**MOT test number** 502666943979**Result** ✓ Passed**MOT #3** 2015-08-04 11:09**MOT test number** 695723999144**Result** ✓ Passed



MOT #2	2015-08-04 10:16
MOT test number	656652540045
Result	✗ Failed
Fail	Offside Registration plate lamp not working (1.1.C.1d)
Fail	Offside Rear brake caliper leaking (3.6.A.1)

MOT #1	2014-09-16 13:31
MOT test number	366569954232
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
24 January 2024

✓

MOT

Expires:
13 January 2025

Tax status	Expired at 24 January 2024
Days left	95 days too late
MOT expiry date	13 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-09-20
Last registration	2023-12-28
Complete history	See info



Registration #1	2011-09-20	12 mi
Registration #2	2014-09-16	30.808 mi
Registration #3	2015-08-04	34.928 mi
Registration #4	2015-08-04	34.928 mi
Registration #5	2016-07-23	39.248 mi
Registration #6	2017-08-11	43.583 mi
Registration #7	2018-07-14	47.455 mi
Registration #8	2019-07-31	54.171 mi
Registration #9	2020-05-20	55.277 mi
Registration #10	2020-05-20	55.277 mi
Registration #11	2020-05-20	55.277 mi
Registration #12	2020-05-20	55.277 mi
Registration #13	2020-05-20	55.277 mi
Registration #14	2020-05-20	55.277 mi
Registration #15	2020-05-20	55.277 mi
Registration #16	2020-05-20	55.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1346 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1038586