



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	MATRIX GSI
Colour	Silver
Year of manufacture	-
Top speed	105 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	141 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	42.8 mpg
Consumption combined	35.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-17
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT #19</b>	2021-12-07 17:03
<b>MOT test number</b>	459883154982
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-12-06
<b>Advice</b>	Outer tailgate handle stiff

<b>MOT #18</b>	2021-12-06 16:22
<b>MOT test number</b>	770068990505
<b>Result</b>	✗ Failed
<b>Advice</b>	Offside Front Service brake binding but not excessively (1.2.1 (f))
<b>Advice</b>	Bonnet hinges stiff
<b>MAJOR</b>	Nearside Front Service brake excessively binding (1.2.1 (f))
<b>Advice</b>	Outer tailgate handle stiff
<b>Minor</b>	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

<b>MOT #17</b>	2020-08-19 09:26
<b>MOT test number</b>	388817838608
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Anti-roll bar pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))
<b>Advice</b>	Offside Rear seat base not clipped in properly requires attention
<b>Advice</b>	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm rear bush (5.3.4 (a) (i))
<b>Advice</b>	Registration plate deteriorated but not likely to be misread front and rear (0.1 (b))

**MOT #16**

2020-08-15 10:36

**MOT test number**

883316519622

**Result****✗ Failed**

**MAJOR** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm worn uneven/flat spots (5.2.3 (e))

**Advice** Free play in handbrake cable

**Advice** Registration plate deteriorated but not likely to be misread front and rear (0.1 (b))

**Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))

**MAJOR** Brake lever has insufficient reserve travel (1.1.2 (a))

**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

**Advice** Offside Rear seat base not clipped in properly requires attention

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm rear bush (5.3.4 (a) (i))

**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #15**

2019-08-02 07:59

**MOT test number**

467379822743

**Result****✓ Passed**

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear rubber bush (5.3.4 (a) (i))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14**

2018-08-02 08:33

**MOT test number**

753599502355

**Result**

✓ Passed

**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Exhaust corroded**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #13**

2018-08-02 07:53

**MOT test number**

120597307868

**Result**

✗ Failed

**Advice** Exhaust corroded**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #12**

2017-08-02 14:29

**MOT test number**

316335208014

**Result**

✓ Passed

**MOT #11**

2017-08-02 14:29

**MOT test number**

922672379849

**Result**

✗ Failed

**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)

**MOT #10** 2016-07-20 11:29**MOT test number** 780096948427**Result** ✓ Passed**MOT #9** 2015-08-03 12:32**MOT test number** 205345015267**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2014-02-05 11:50**MOT test number** 848806334073**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2012-11-08 12:32**MOT test number** 228473512356**Result** ✓ Passed**MOT #6** 2011-10-26 08:38**MOT test number** 295449091249**Result** ✓ Passed**MOT #5** 2011-10-25 08:48**MOT test number** 879938191276**Result** ✗ Failed**Fail** Nearside Rear Valve stem seriously damaged (4.1.D.1e)



MOT #4	2010-10-27 11:16
MOT test number	480320800393
Result	✓ Passed
MOT #3	2009-10-30 15:27
MOT test number	400223609413
Result	✓ Passed
MOT #2	2008-10-22 14:42
MOT test number	600526998227
Result	✓ Passed
MOT #1	2007-08-23 11:20
MOT test number	200485637232
Result	✓ Passed



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>WX54EEZ</b>
Plate since	2024-03-29
Current registration	<b>WX54EEZ</b>
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2004-09-01
Last registration	2021-12-07
Complete history	<a href="#">See info</a>



Registration #1	2004-09-01	7 mi
Registration #2	2007-08-23	17.073 mi
Registration #3	2008-10-22	17.453 mi
Registration #4	2009-10-30	17.961 mi
Registration #5	2010-10-27	18.267 mi
Registration #6	2011-10-25	18.491 mi
Registration #7	2012-11-08	19.257 mi
Registration #8	2014-02-05	21.921 mi
Registration #9	2015-08-03	24.984 mi
Registration #10	2016-07-20	32.951 mi
Registration #11	2016-08-20	33.377 mi
Registration #12	2016-09-20	33.803 mi
Registration #13	2016-10-20	34.229 mi
Registration #14	2016-11-20	34.655 mi
Registration #15	2016-12-20	35.081 mi
Registration #16	2017-01-20	35.507 mi
Registration #17	2017-02-20	35.933 mi
Registration #18	2017-03-20	36.359 mi
Registration #19	2017-04-20	36.785 mi
Registration #20	2017-05-20	37.211 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1740 mm
Height	1625 mm
Length	4025 mm
Wheel base	2600 mm
Kerb weight	1327 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	G4ED4837364