



BDIIJHF

report date: 2024-03-29

General information

Make	CITROEN
Model	C5 E-HDI VTR PLUS NAV
Colour	Black
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	12.6 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	58.9 mpg
CO2 emission	120 g/km
CO2 label	C





Internet history

Entry 1

Date	2022-07-29
Pictures	42
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-31
MOT pass rate	59 %
MOT passed	10
Failed MOT tests	7
Total advice items	37
Total items failed	11

MOT #17 2023-08-01 14:17

MOT test number 102427495305

Result ✓ Passed

Next expiry date 2024-07-31

Advice Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #16 2023-07-31 15:39

MOT test number 573932723759

Result ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Lower Suspension arm ball joint excessively worn bearing (5.3.4 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #15** 2022-08-01 14:15**MOT test number** 398934548247**Result** ✓ Passed**MOT #14** 2021-11-09 10:58**MOT test number** 851917545771**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #13** 2021-11-09 10:58**MOT test number** 826034747728**Result** ✗ Failed**Pass with rectification** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Pass with rectification** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Pass with rectification** Nearside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #12** 2020-11-26 14:03**MOT test number** 722492777283**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

**MOT #11** 2020-11-26 12:02**MOT test number** 239962658596**Result** ✗ Failed**Advice** Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #10** 2019-05-20 13:08**MOT test number** 688541600642**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin Both, Inner (1.1.13 (a) (ii))**MOT #9** 2019-05-20 13:08**MOT test number** 489378534252**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin Both, Inner (1.1.13 (a) (ii))**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively Both (3.4 (b) (ii))**MOT #8** 2018-05-30 11:00**MOT test number** 784448911598**Result** ✓ Passed**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #7** 2017-05-25 15:59**MOT test number** 906641108029**Result** ✓ Passed**Advice** Front Inner Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2017-05-24 09:05**MOT test number** 750328935194**Result** ✗ Failed**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Front Inner Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Tyre worn low on edges**Advice** Nearside Rear Inner Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**MOT #5** 2016-05-23 10:57**MOT test number** 997731567013**Result** ✓ Passed**Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)**Advice** Nearside Rear Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)

**MOT #4** 2015-04-23 15:59**MOT test number** 977313515124**Result** ✓ Passed**Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)**Notice** Offside front tyre worn low outside centre 3/4**Advice** Offside Track rod end ball joint has slight play (2.2.B.1f)**Notice** Offside front fog light does not work**MOT #3** 2015-04-23 15:59**MOT test number** 638913415130**Result** ✗ Failed**Notice** Offside front tyre worn low outside centre 3/4**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Track rod end ball joint has slight play (2.2.B.1f)**Notice** Offside front fog light does not work**Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)**MOT #2** 2014-05-21 08:56**MOT test number** 487241244116**Result** ✓ Passed**MOT #1** 2014-05-21 08:56**MOT test number** 896361044128**Result** ✗ Failed**Pass with rectification** Nearside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
31 July 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	31 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-04-15
Last registration	2023-08-01
Complete history	See info



Registration #1	2011-04-15	24 mi
Registration #2	2014-05-21	61.954 mi
Registration #3	2015-04-23	78.528 mi
Registration #4	2016-05-23	84.338 mi
Registration #5	2017-05-24	86.811 mi
Registration #6	2017-05-25	86.916 mi
Registration #7	2018-05-30	87.412 mi
Registration #8	2019-05-20	101.151 mi
Registration #9	2019-05-20	101.151 mi
Registration #10	2019-05-20	101.151 mi
Registration #11	2019-05-20	101.151 mi
Registration #12	2019-05-20	101.151 mi
Registration #13	2019-05-20	101.151 mi
Registration #14	2019-05-20	101.151 mi
Registration #15	2019-05-20	101.151 mi
Registration #16	2019-05-20	101.151 mi
Registration #17	2019-05-20	101.151 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	81%
Children	77%
Pedestrian	32%
Safety systems	83%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	1860 mm
Height	1458 mm
Length	4779 mm
Wheel base	2815 mm
Kerb weight	1525 kg
Max. allowed weight	2062 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	JBDJ3000975