



**SB59XB0**

report date: 2024-03-29

General information

Make	MAZDA
Model	6 TS
Colour	Grey
Year of manufacture	2009
Top speed	123 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	165 Nm at 4.300 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	53.3 mpg
Consumption combined	40.9 mpg
CO2 emission	159 g/km
CO2 label	G





## MOT history

MOT expiry date	2021-09-16
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	31
Total items failed	10

## MOT #14 2020-09-17 12:24

MOT test number 281113121547

Result ✓ Passed

Next expiry date 2021-09-16

**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

## MOT #13 2020-09-16 12:39

MOT test number 662512430676

Result ✗ Failed**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Minor** Windscreen wiper blade defective (3.4 (b) (i))**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))**Fail** Battery insecure and likely to fall from carrier (4.13 (a) (ii))

## MOT #12 2019-09-12 11:43

MOT test number 665389325050

Result ✓ Passed

**MOT #11**

2018-09-01 13:51

**MOT test number**

123514355870

**Result**

✓ Passed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear Brake pad(s) wearing thin both (1.1.13 (a) (ii))
- Advice** Front Suspension arm corroded but not seriously weakened both (5.3.3 (b) (i))
- Minor** Front Windscreen wiper blade defective (3.4 (b) (i))

**MOT #10**

2018-09-01 13:51

**MOT test number**

776084682093

**Result**

✗ Failed

- Advice** Rear Brake pad(s) wearing thin both (1.1.13 (a) (ii))
- Advice** Offside Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))
- Minor** Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Front Suspension arm corroded but not seriously weakened both (5.3.3 (b) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))

**MOT #9** 2017-09-08 16:40**MOT test number** 197238966883**Result** ✓ Passed**MOT #8** 2017-09-08 08:18**MOT test number** 603424553123**Result** ✗ Failed**Fail** Offside Rear Anti-roll bar linkage fractured (2.4.G.1)**MOT #7** 2016-09-07 14:57**MOT test number** 450234417989**Result** ✓ Passed**MOT #6** 2015-09-09 11:44**MOT test number** 397624444717**Result** ✓ Passed**MOT #5** 2014-08-21 17:16**MOT test number** 799683334228**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Offside rear tyre punctured on shoulder

**MOT #4** 2014-08-21 13:12**MOT test number** 225253534209**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Offside rear tyre punctured on shoulder**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-08-30 14:41**MOT test number** 716202543266**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #2** 2012-08-30 17:17**MOT test number** 315003042459**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #12012-08-30 17:17

MOT test number685243242228

Result

Failed

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification

Offside Registration plate lamp insecure (1.1.C.1c)

Pass with rectification

Offside Headlamp aim too high (1.8)

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification

Nearside Registration plate lamp insecure (1.1.C.1c)

Pass with rectification

Nearside Headlamp aim too high (1.8)



Tax & MOT check

✕  
Untaxed

Tax expired:  
3 February 2021

✕  
MOT

Expired:  
16 September 2021

Tax status	Expired at 3 February 2021
Days left	1181 days too late
MOT expiry date	16 September 2021
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-12-30
Last registration	2020-09-17
Complete history	<a href="#">See info</a>



Registration #1	2009-12-30	18 mi
Registration #2	2012-08-30	19.238 mi
Registration #3	2013-08-30	35.938 mi
Registration #4	2014-08-21	49.002 mi
Registration #5	2014-08-21	49.002 mi
Registration #6	2015-09-09	60.498 mi
Registration #7	2016-09-07	72.500 mi
Registration #8	2016-09-07	72.500 mi
Registration #9	2016-09-07	72.500 mi
Registration #10	2016-09-07	72.500 mi
Registration #11	2016-09-07	72.500 mi
Registration #12	2016-09-07	72.500 mi
Registration #13	2016-09-07	72.500 mi
Registration #14	2016-09-07	72.500 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	77%
Children	81%
Pedestrian	49%
Safety systems	71%
Overall rating	72%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1795 mm
Height	1440 mm
Length	4755 mm
Wheel base	2725 mm
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	L8 20262349