



report date: 2024-03-29

General information

Make	FORD
Model	FUSION FUSION 1
Colour	Silver
Year of manufacture	-
Top speed	99 mph
0 - 60 mph	15.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	160 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	72.4 mpg
Consumption combined	64.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-05-22
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #19	2022-11-15 15:05
MOT test number	409139942074
Result	✓ Passed
Next expiry date	2023-11-14
Advice	EXHAUST GAS LEAK FROM INJECTOR
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Suspension arm pin or bush worn but not resulting in excessive movement BOTH (5.3.4 (a) (i))

MOT #18	2022-11-14 10:29
MOT test number	640981867191
Result	✗ Failed
Advice	Rear Suspension arm pin or bush worn but not resulting in excessive movement BOTH (5.3.4 (a) (i))
Fail	Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))
Advice	EXHAUST GAS LEAK FROM INJECTOR
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17	2021-11-15 11:53
MOT test number	707552669263
Result	✓ Passed
MOT #16	2020-11-14 15:52
MOT test number	784681322065
Result	✓ Passed

Advice Front Exhaust has a minor leak of exhaust gases in engine bay (6.1.2 (a))

Advice Brake pipe corroded, covered in grease or other material Front to rear (all corners) (1.1.11 (c))

Advice Offside Rear impact damage to bumper and tailgate only

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn cracked and split,slight play (5.1.2 (b) (i))

**MOT #15**

2020-11-12 12:46

MOT test number

261961882263

Result**✗ Failed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge bald on inner edge, no cords (5.2.3 (e))**Advice** Brake pipe corroded, covered in grease or other material Front to rear (all corners) (1.1.11 (c))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Front Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Advice** Front Exhaust has a minor leak of exhaust gases in engine bay (6.1.2 (a))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Tyre has ply or cords exposed Osf and both rear tyres (5.2.3 (d) (ii))**Advice** Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn cracked and split,slight play (5.1.2 (b) (i))**Pass with rectification** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Rear impact damage to bumper and tailgate only**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #14**

2019-04-09 15:49

MOT test number

587976879381

Result

✓ Passed

- Advice** Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Nearside and offside front brake pipes corroding
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive axle bush area (5.3.6 (a) (i))
- Advice** Rear brake hoses cracking
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm, tyre also wearing on edges (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3mm, tyre also wearing on outer edge (5.2.3 (e))
- Advice** Nearside Front dip beam image faded, headlamp misted
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Rear brake pipe corroding
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm, tyre also cracked and wearing on outer edge (5.2.3 (e))

**MOT #13**

2019-04-09 08:46

MOT test number

333115155012

Result**✗ Failed**

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear brake hoses cracking
- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm, tyre also cracked and wearing on outer edge (5.2.3 (e))
- Advice** Nearside Front dip beam image faded, headlamp misted
- Fail** Exhaust has a major leak of exhaust gases centre pipe (6.1.2 (a))
- Advice** Nearside Rear brake pipe corroding
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive axle bush area (5.3.6 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm, tyre also wearing on edges (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3mm, tyre also wearing on outer edge (5.2.3 (e))
- Advice** Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Nearside and offside front brake pipes corroding

MOT #12

2018-04-14 14:54

MOT test number

872531052322

Result**✓ Passed**

- Advice** Offside Rear Tyre worn close to the legal limit cracked badly (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit cracked badly (4.1.E.1)

**MOT #11**

2018-04-05 11:56

MOT test number

752355832817

Result**✗ Failed**

- Fail** Nearside Rear Fluid suspension unit leaking shock (2.4.D.2)
- Fail** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit cracked badly (4.1.E.1)
- Fail** Nearside Front Direction indicators incorrect colour (1.4.A.2f)
- Advice** Offside Rear Tyre worn close to the legal limit cracked badly (4.1.E.1)

MOT #10

2016-08-26 09:20

MOT test number

839012569856

Result**✓ Passed**

- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)

MOT #9

2015-08-13 08:58

MOT test number

733237962561

Result**✓ Passed**

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Nail in tyre

MOT #8

2014-08-22 11:55

MOT test number

506304034287

Result**✓ Passed**

**MOT #7** 2013-09-04 11:19**MOT test number** 185667243293**Result** ✓ Passed**MOT #6** 2013-09-02 10:41**MOT test number** 478085143244**Result** ✗ Failed

- Fail** Centre Stop lamp not working (1.2.1b)
- Fail** Nearside Stop lamp not working (1.2.1b)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #5 2012-11-13 15:15**MOT test number** 406878912379**Result** ✓ Passed

- Notice** Items removed from driver's view prior to test
- Notice** Damaged to o/s front

MOT #4 2011-10-05 12:46**MOT test number** 417718671264**Result** ✓ Passed

- Notice** Front bumper is damaged
- Notice** Offside and nearside rear coil spring are corroded at the bottom
- Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Offside and nearside front brake discs are slightly worn
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)



MOT #3	2010-07-05 13:01
MOT test number	352356780171
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2009-02-05 14:54
MOT test number	572596039062
Result	✓ Passed

MOT #1	2007-10-24 14:49
MOT test number	343557597222
Result	✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2004-11-30
Last registration	2022-11-15
Complete history	See info



Registration #1	2004-11-30	26 mi
Registration #2	2007-10-24	23.524 mi
Registration #3	2009-02-05	32.962 mi
Registration #4	2010-07-05	41.728 mi
Registration #5	2011-10-05	50.176 mi
Registration #6	2012-11-13	59.957 mi
Registration #7	2013-09-02	65.303 mi
Registration #8	2013-09-04	65.309 mi
Registration #9	2014-08-22	73.199 mi
Registration #10	2015-08-13	84.251 mi
Registration #11	2016-08-26	94.686 mi
Registration #12	2019-05-20	95.377 mi
Registration #13	2019-05-20	95.377 mi
Registration #14	2019-05-20	95.377 mi
Registration #15	2019-05-20	95.377 mi
Registration #16	2019-05-20	95.377 mi
Registration #17	2019-05-20	95.377 mi
Registration #18	2019-05-20	95.377 mi
Registration #19	2019-05-20	95.377 mi
Registration #20	2019-05-20	95.377 mi
Registration #21	2019-05-20	95.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1952 mm
Height	1534 mm
Length	4020 mm
Wheel base	2485 mm
Kerb weight	1102 kg
Max. allowed weight	1640 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

4D03147