



report date: 2024-03-28

General information

Make	KIA
Model	SEDONA CRDI GS
Colour	Blue
Year of manufacture	-
Top speed	121 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	182 BHP
Max. torque	343 Nm at 3.500 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	23.9 mpg
Consumption extra urban	28.5 mpg
Consumption combined	32.5 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-27
Pictures	32
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #10	2022-06-23 14:44
MOT test number	503812751891
Result	✓ Passed
Next expiry date	2023-06-22
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Front Tyre slightly damaged/cracking or perishing BOTH (5.2.3 (d) (ii))
Minor	Nearside Front Battery insecure but not likely to fall from carrier (4.13 (a) (i))
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement BOTH (5.3.4 (a) (i))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #9	2022-06-23 14:40
MOT test number	331233300154
Result	✗ Failed
Minor	Nearside Front Battery insecure but not likely to fall from carrier (4.13 (a) (i))
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement BOTH (5.3.4 (a) (i))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Front Tyre slightly damaged/cracking or perishing BOTH (5.2.3 (d) (ii))
Fail	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))

MOT #8	2021-05-23 14:50
MOT test number	395952823413
Result	✓ Passed
Advice	Vehicle undersealed

**MOT #7** 2019-04-01 16:29**MOT test number** 509245375514**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened front and rear (1.1.14 (a) (ii))**MOT #6** 2016-07-16 13:34**MOT test number** 108153954006**Result** ✓ Passed**Advice** Obligatory mirror damaged, but not seriously affecting the rear view offside**MOT #5** 2015-09-11 12:57**MOT test number** 612397891042**Result** ✓ Passed**Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**MOT #4** 2015-09-11 09:55**MOT test number** 920158100903**Result** ✗ Failed**Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #3** 2014-09-16 12:50**MOT test number** 779499954254**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



MOT #2	2013-09-17 14:24
MOT test number	369490963298
Result	✓ Passed

MOT #1	2012-09-14 12:46
MOT test number	167778652287
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	LT09LZH
Plate since	2019-09-28
Current registration	LT09LZH
Plate since	2019-09-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2009-04-09
Last registration	2022-06-23
Complete history	See info



Registration #1	2009-04-09	7 mi
Registration #2	2012-09-14	30.637 mi
Registration #3	2013-09-17	41.131 mi
Registration #4	2014-09-16	56.253 mi
Registration #5	2015-09-11	66.269 mi
Registration #6	2015-09-11	66.270 mi
Registration #7	2015-09-11	66.270 mi
Registration #8	2015-09-11	66.270 mi
Registration #9	2015-09-11	66.270 mi
Registration #10	2015-09-11	66.270 mi
Registration #11	2015-09-11	66.270 mi
Registration #12	2015-09-11	66.270 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1985 mm
Height	1815 mm
Length	4810 mm
Wheel base	2890 mm
Kerb weight	2189 kg
Max. allowed weight	2920 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	J3 8 289347