





report date: 2024-03-28

### General information

| Make                | SUZUKI         |
|---------------------|----------------|
| Model               | SPLASH SZ2     |
| Colour              | Red            |
| Year of manufacture | 2013           |
| Top speed           | 99 mph         |
| 0 - 60 mph          | 14.7 seconds   |
| Gearbox             | 5 speed Manual |

### Engine & fuel consumption

| Power                   | 67 BHP             |
|-------------------------|--------------------|
| Max. torque             | 90 Nm at 4.800 rpm |
| Engine capacity         | 996 cc             |
| Cylinders               | 3                  |
| Fuel type               | Petrol             |
| Consumption city        | 50.4 mpg           |
| Consumption extra urban | 67.3 mpg           |
| Consumption combined    | 60.1 mpg           |
| CO2 emission            | 109 g/km           |
| CO2 label               | В                  |



CarCheck.co.uk page 1/11



report date: 2024-03-28

| MOT h | nistory |
|-------|---------|
|-------|---------|

| MOT expiry date    | 2025-04-08 |
|--------------------|------------|
| MOT pass rate      | 73 %       |
| MOT passed         | 8          |
| Failed MOT tests   | 3          |
| Total advice items | 2          |
| Total items failed | 8          |

| MOT #11          | 2024-04-05 13:43 |
|------------------|------------------|
| MOT test number  | 462345046325     |
| Result           | <b>✓</b> Passed  |
| Next expiry date | 2025-04-08       |

| MOT #10         | 2023-04-06 13:48 |
|-----------------|------------------|
| MOT test number | 702213357419     |
| Result          | ✓ Passed         |

| MOT #9          | 2022-04-07 08:38 |
|-----------------|------------------|
| MOT test number | 831366942345     |
| Result          | <b>✓</b> Passed  |

| MO1 #0 |                         | 2022-04-07 00.50  |
|--------|-------------------------|---|
|        | MOT test number         | 279181504465  |
|        | Result                  | <b>X</b> Failed   |
|        | Pass with rectification | Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) |
|        | Pass with rectification | Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))        |

Pass with rectification Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT #7 2021-04-09 13:44

**MOT test number** 680556924847

**MOT #6** 2021-04-09 07:49

MOT test number 272221527929

Result X Failed

Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Battery insecure and likely to fall from carrier (4.13 (a) (ii))

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #5** 2020-01-11 10:46

**MOT test number** 997610188694

Result \rightarrow Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge & offside outer edges (5.2.3 (e))

MOT #4 2019-01-19 12:04

**MOT test number** 457436932166

Result 

Passed

MOT #3 2018-01-13 10:05

MOT test number 935882166774

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2017-01-25 15:19

**MOT test number** 626295052085

CarCheck.co.uk page 3/11



report date: 2024-03-28

**MOT #1** 2017-01-25 15:19

**MOT test number** 940130352731

**Result** X Failed

**Pass with rectification** 

Central Front Windscreen washer provides insufficient washer liquid (8.2.3)

CarCheck.co.uk page 4/11



BX63XMY report date: 2024-03-28

Tax & MOT check



| Tax status       | Valid until 1 August |
|------------------|----------------------|
| Days left        | 95                   |
| MOT expiry date  | 8 April 2025         |
| Full MOT history | See MOT history      |

### Tax calculation

| Vehicle class                           | 48             |
|---|----------------|
| Band                                    | В              |
| Single payment (12 months)              | £ 20,00,-      |
| Single six month payment                | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,-      |

CarCheck.co.uk page 5/11



report date: 2024-03-28

### Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

### Owner history

| For how long did the current and previous owner(s) have this SUZUKI? How many owners have? Check it in the premium report and see all owner registrations. Download the full is |             |
|---|-------------|
| ********  |             |
|   |             |
| ***************************************   |             |
| *********   |             |
|   |             |
|   |             |
|   | More info > |
| Plate changes   |             |
| See in this check if this SUZUKI had different number plates.   |             |
| Number of plates  | ,           |
| Current registration  | AIS UK      |
| Plate since   |             |
| Current registration  | UK NIE      |
| Plate since   |             |
|   | More info > |

CarCheck.co.uk page 8/11



BX63XMY report date: 2024-03-28

### Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

## Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 12         |
| First mileage registration | 2013-09-28 |
| Last registration          | 2024-04-05 |
| Complete history           | See info   |



| Registration #1  | 2013-09-28 | 27 mi     |
|------------------|------------|-----------|
| Registration #2  | 2017-01-25 | 22.765 mi |
| Registration #3  | 2017-01-25 | 22.765 mi |
| Registration #4  | 2018-01-13 | 41.977 mi |
| Registration #5  | 2019-01-19 | 60.934 mi |
| Registration #6  | 2020-01-11 | 80.286 mi |
| Registration #7  |            | 11.777 es |
| Registration #8  |            | 11.777 es |
| Registration #9  |            | 11.777 es |
| Registration #10 |            | 11.777 es |
| Registration #11 |            | 11.777 es |
| Registration #12 |            |           |

More info >

CarCheck.co.uk page 10/11



BX63XMY report date: 2024-03-28

### Safety ratings

| NCAP rating | ***             |
|-------------|-----------------|
| Video       | see crash video |



# Dimensions & weight

| Width               | 1680 mm |
|---------------------|---------|
| Height              | 1590 mm |
| Length              | 3715 mm |
| Wheel base          | 2360 mm |
| Kerb weight         | 1075 kg |
| Max. allowed weight | 1485 kg |

### Additional information

| Fuel tank capacity | 45 l                  |
|--------------------|-----------------------|
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 5                     |
| Number of seats    | 5                     |
| Engine number      | K10BN1670781          |

CarCheck.co.uk page 11/11