



report date: 2024-03-28

General information

Make	KIA
Model	CARENS GS
Colour	Black
Year of manufacture	-
Top speed	115 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	175 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	41.5 mpg
Consumption combined	34.9 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-09
Pictures	10
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #18</b>	2022-10-13 13:13
<b>MOT test number</b>	984815558120
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-11-04
<b>Advice</b>	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
<b>Advice</b>	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
<b>Advice</b>	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
<b>Minor</b>	Battery insecure but not likely to fall from carrier (4.13 (a) (i))
<b>Advice</b>	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
<b>Advice</b>	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

<b>MOT #17</b>	2022-10-06 09:35
<b>MOT test number</b>	717981780703
<b>Result</b>	✗ Failed
<b>Fail</b>	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
<b>Minor</b>	Battery insecure but not likely to fall from carrier (4.13 (a) (i))
<b>Advice</b>	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
<b>Fail</b>	Nearside Front Inner Tyre has a tear, caused by separation or partial failure of its structure edge (5.2.3 (d) (ii))
<b>Advice</b>	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
<b>Fail</b>	Parking brake efficiency below requirements (1.4.2 (a) (i))
<b>Fail</b>	Rear Exhaust emissions likely to be affected by an exhaust leak exhaust box (8.2.1.1 (b))
<b>Advice</b>	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
<b>Advice</b>	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
<b>Fail</b>	Nearside Rear Inner Tyre has a tear, caused by separation or partial failure of its structure edge (5.2.3 (d) (ii))
<b>Advice</b>	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #16** 2021-11-05 15:15**MOT test number** 207575069854**Result** ✓ Passed**Advice** Brake pedal anti-slip 20% worn**Advice** Offside Front Brake pad(s) wearing thin inner and outer disc pads (1.1.13 (a) (ii))**MOT #15** 2021-11-01 11:58**MOT test number** 548450512992**Result** ✗ Failed**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Front Brake pad(s) wearing thin inner and outer disc pads (1.1.13 (a) (ii))**Fail** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Offside Front Service brake excessively binding when vehicle jacked and wheel rotated (1.2.1 (f))**Fail** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Pass with rectification** Offside Front Headlamp aim too high and too far to the left. (4.1.2 (a))**Fail** Nearside Rear Service brake excessively binding when vehicle jacked and wheel rotated (1.2.1 (f))**Advice** Brake pedal anti-slip 20% worn**Fail** Offside Rear Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting outer sill section (6.2.2 (d) (i))

**MOT #14**

2020-11-05 09:02

**MOT test number**

626609471504

**Result**

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear Exhaust mounting defective modified. Hangs low but not likely to detach (6.1.2 (a))
- Minor** Brake warning device malfunctioning or defective (1.1.4 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))

**MOT #13**

2020-10-29 12:02

**MOT test number**

720447779717

**Result**

✗ Failed

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear Exhaust mounting defective modified. Hangs low but not likely to detach (6.1.2 (a))
- Minor** Brake warning device malfunctioning or defective (1.1.4 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12**

2020-09-22 14:12

**MOT test number**

728183985249

**Result**

✗ Failed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Exhaust secure but hangs low
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #11**

2019-08-28 11:28

**MOT test number**

469751341095

**Result**

✓ Passed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #10**

2018-08-03 09:22

**MOT test number**

592427632811

**Result**

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9**

2017-08-14 08:37

**MOT test number**

981224517470

**Result**

✓ Passed

- Advice** Nearside Front worn on inner edge ok at time of test

**MOT #8** 2016-08-10 08:59**MOT test number** 782398335754**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit inner eage (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit inner eage (4.1.E.1)**MOT #7** 2015-08-13 10:07**MOT test number** 668885725249**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2014-08-06 13:02**MOT test number** 578478514249**Result** ✓ Passed**Notice** Back box bracket broken but system still supported**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2013-08-01 08:56**MOT test number** 355773713452**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Notice** All tyres fitted to vehicle slightly perished

**MOT #4** 2012-08-15 09:48**MOT test number** 335698122450**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #3** 2011-08-04 11:15**MOT test number** 818576311253**Result** ✓ Passed**Advice** Nearside Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #2** 2010-08-02 08:55**MOT test number** 892524910242**Result** ✓ Passed**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #1** 2009-07-30 08:33**MOT test number** 363391319279**Result** ✓ Passed**Notice** Nail in offside rear tyre





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-08-12
Last registration	2022-10-13
Complete history	<a href="#">See info</a>



Registration #1	2006-08-12	7 mi
Registration #2	2009-07-30	6.199 mi
Registration #3	2010-08-02	10.269 mi
Registration #4	2011-08-04	14.280 mi
Registration #5	2012-08-15	18.271 mi
Registration #6	2013-08-01	22.213 mi
Registration #7	2014-08-06	27.338 mi
Registration #8	2015-08-13	33.328 mi
Registration #9	2016-08-10	37.238 mi
Registration #10	2017-08-14	43.114 mi
Registration #11	2018-08-14	49.000 mi
Registration #12	2019-08-14	54.886 mi
Registration #13	2020-08-14	60.771 mi
Registration #14	2021-08-14	66.657 mi
Registration #15	2022-08-14	72.543 mi
Registration #16	2023-08-14	78.429 mi
Registration #17	2024-08-14	84.314 mi
Registration #18	2025-08-14	90.200 mi
Registration #19	2026-08-14	96.086 mi
Registration #20	2027-08-14	101.971 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1748 mm
Height	1650 mm
Length	4493 mm
Wheel base	2560 mm
Kerb weight	1475 kg
Max. allowed weight	1890 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	G4GC5H32175