




report date: 2024-03-29

General information

Make	NISSAN
Model	NV400 DCI SE SHR C/C
Colour	White
Year of manufacture	2017
Top speed	92 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	2.298 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	37.7 mpg
Consumption combined	34.5 mpg
CO2 emission	212 g/km
CO2 label	K





Internet history

Entry 1

Date	2022-07-05
Pictures	11
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-29
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	18
Total items failed	2

MOT #7	2024-03-26 08:06
MOT test number	312394623139
Result	✓ Passed
Next expiry date	2025-03-29
Advice	Nearside Front marker light out
Minor	Nearside Front Obligatory mirror slightly damaged (3.3 (b) (i))
Minor	Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #6	2024-03-26 08:06
MOT test number	984320835510
Result	✗ Failed
Pass with rectification	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
Minor	Nearside Front Obligatory mirror slightly damaged (3.3 (b) (i))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Nearside Front marker light out
Minor	Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #5** 2023-03-30 11:53**MOT test number** 435441333408**Result** ✓ Passed**Minor** Nearside Front Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Central Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #4** 2023-03-29 07:16**MOT test number** 513905838912**Result** ✗ Failed**MAJOR** Nearside Outline marker lamp with a multiple light source more than 1/2 not functioning (4.2.1 (a) (ii))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Front Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Central Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MAJOR** Nearside Front Side repeater not working (4.4.1 (a) (ii))**Advice** Rear Inner Brake pad(s) wearing thin n/s & o/s (1.1.13 (a) (ii))**MOT #3** 2022-01-06 10:43**MOT test number** 500689235264**Result** ✓ Passed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #2** 2021-01-08 15:52**MOT test number** 645915887920**Result** ✓ Passed



MOT #1	2021-01-08 09:34
MOT test number	352720623820
Result	✗ Failed
<div><div>DANGEROUS</div><div>Rear Brake pad(s) less than 1.5 mm thick offside and nearside (1.1.13 (a) (ii))</div></div>	



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
29 March 2025

Tax status	Valid until 1 July
Days left	63
MOT expiry date	29 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-



Damage history


Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-10-31
Last registration	2024-03-26
Complete history	See info



Registration #1	2017-10-31	23 mi
Registration #2	2021-01-08	35.201 mi
Registration #3	2021-01-08	35.218 mi
Registration #4	2022-01-06	50.699 mi
Registration #5	2023-03-26	55.277 mi
Registration #6	2023-03-26	55.277 mi
Registration #7	2023-03-26	55.277 mi
Registration #8	2023-03-26	55.277 mi
Registration #9	2023-03-26	55.277 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2070 mm
Height	2258 mm
Length	6199 mm
Wheel base	3682 mm
Kerb weight	1735 kg
Max. allowed weight	3500 kg

Additional information

Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	MBT-040234