





report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 DSTYLE PLUS
Colour	Red
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.200 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	57.7 mpg
Consumption combined	43.5 mpg
CO2 emission	150 g/km
CO2 label	F



CarCheck.co.uk page 1/14




Internet history

Entry 1

Date 2021-07-21

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-06-30
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	45
Total items failed	0

MOT #12		2023-07-01 12:08
MOT test	number	929965179717
Result		✓ Passed
Next expi	ry date	2024-06-30
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	

MOT #11		2023-07-01 11:31
MOT test	number	701577377530
Result		X Failed
MAJOR	Offside Front Position lamp not working (4.2.1 (a) (ii))	
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
DANGER sidewall (5	Nearside Rear Tyre has a tear, caused by separation or partial failur 5.2.3 (d) (ii))	e of its structure Inner
MAJOR	Offside Front Road wheel fixing missing (5.2.1 (a) (i))	
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Minor (i))	Offside Registration plate lamp inoperative in the case of multiple lamps or	light sources (4.7.1 (b)

MOT #10	2022-06-12 19:07
MOT test number	428470187922
Result	✓ Passed

CarCheck.co.uk page 3/14



MOT #9 2022-06-12 11:09

MOT test number 359853022962

Result × Failed

MAJOR Offside Headlamp not working on main beam (4.1.1 (a) (ii))

DANGEROUS Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MAJOR Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))

MAJOR Rear Exhaust silencer insecure (8.1.1 (b) (i))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MAJOR Headlamp aim not tested aim could not be tested due to lamps not working (4.1.2 (b))

MAJOR Nearside Headlamp not working on main beam (4.1.1 (a) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened worn and pitted (1.1.14 (a) (ii))

MAJOR Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Rear Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #8 2021-05-19 13:00

MOT test number 898507421659

Result / Passed

Advice Nearside Front Wing damaged

Advice Exhaust has a minor leak of exhaust gases back box (6.1.2 (a))

CarCheck.co.uk page 4/14



MOT #7 2021-05-19 10:10

MOT test number 204505099325

Result X Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge both edges worn smooth (5.2.3 (e))

Advice Exhaust has a minor leak of exhaust gases back box (6.1.2 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

Advice Nearside Front Wing damaged

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2020-06-17 15:06

MOT test number 635923217006

Result
✓ Passed

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice T.P.M.S light illuminated.

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Exhaust mounting defective (6.1.2 (a))

CarCheck.co.uk page 5/14



MOT #5 2020-06-17 14:18

MOT test number 215822726959

Result X Failed

MAJOR Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

DANGEROUS Nearside Rear Inner Tyre has ply or cords exposed Sidewall (5.2.3 (d) (ii))

Advice Rear Exhaust mounting defective (6.1.2 (a))

Advice Vehicles internal headlight adjuster altered to recheck lights

Advice T.P.M.S light illuminated.

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #4 2019-10-21 14:58

MOT test number 328493707469

Result
✓ Passed

MOT #3 2019-10-21 14:40

MOT test number 451244588856

Result X Failed

Advice Items removed from driver's view prior to test

MAJOR Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MAJOR Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #2 2018-09-24 12:41

MOT test number 556243912230

Result
✓ Passed

CarCheck.co.uk page 6/14



MOT test number

Result

Advice Nearside Rear tyre sidewall damaged due to being run low on pressure

Advice Damage to both front tyre sidewalls

Advice Offside Rear Nail in tyre

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	30 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full respectively.	
THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	OK OK
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 12/14



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-12-09
Last registration	2023-07-01
Complete history	See info



Registration #1	2014-12-09	12 mi
Registration #2	2017-11-09	21.577 mi
Registration #3	2018-09-24	29.743 mi
Registration #4	2019-10-21	35.306 mi
Registration #5	2019-10-21	35.306 mi
Registration #6	2020-06-17	39.264 mi
Registration #7	2020-06-17	39.264 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 13/14



Safety ratings

NCAP rating	****
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1145 kg
Max. allowed weight	1587 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	FHCK2056302

CarCheck.co.uk page 14/14